

ABB Automation Products GmbH

Wallstadter Str. 59

68526 Ladenburg, Germany Telephone: +49 62 21 701 1444

Fax: +49 62 21 701 1382 email: plc.sales@de.abb.com Internet: www.abb.com/plc

3ADR023057M0202, 2, en\_US

<sup>©</sup> Copyright 2015 ABB. All rights reserved. Subject to alterations.

# **Table of contents**

## **Table of contents**

1	Changes CPU Firmware V2.4.2		. 5
	1.1	Improvements	5
	1.2	New Features	6

## **Table of contents**

## 1 Changes CPU Firmware V2.4.2

### 1.1 Improvements

The following improvements have been included in Firmware

V2.4.2.

**C-Code** Some problems have been fixed for relocation of data or pointer

initialization. Fixed.

**EtherCAT** The recognition of data type SINT by the XML parser is now

working. Fixed.

**Ethernet** Improvement of Ethernet stability. Fixed.

UDP protocol: Unconnected Input Data of a FB

"ETH\_UDP\_STD\_SEND" was not well supported by AC500. Fixed,

FTP server with AC500-eCo behavior has been improved in case

of bootproject without task configuration. Fixed

Online Access MCPU load (POU and PLC browser command) show wrong value

in case of high CPU load and is not updated at 100 %. Fixed.

Real-time Clock RTC POU: CurTimeEx does not work correct. Fixed.

System Projects without task configuration use "DefaultTask" (Prio=10,

Cycle time=10 ms, Watchdog=On, Watchdog time=10 ms, Watchdog sensibility=1). This can lead to trigger the watchdog

especially on small PM5xx. Fixed.

Task configuration: Project without task configuration has a default

task running at 10 ms interval with a 10 ms watchdog. The

watchdog is triggered in projects with CS31-Bus or other communi-

cations, especially on small CPUs. Fixed.

Diagnostic message from CM574 communication module in mixed configuration together with other CM577 (e.g.) delivers bad infor-

mation. Fixed .

Serial Communication A runtime error occurred while using the Function Block

COM\_MOD\_MAST via Communication Module CM574-RS when the response time of the slave is longer than the timeout set for the

Function Block. Fixed.

**File Handling** CAA\_File library: ZipArchive\* interface does not work if entries

inside of zip-archive contain slashes ("/") instead of backslashes

("\"). Fixed.

### **Changes CPU Firmware V2.4.2**

**New Features** 

#### 1.2 New Features

The following new features have been added in Firmware V2.4.2.

**System Extension** New display Firmware for AC500 CPU PM57x/PM58x/PM590...

PM592, allowing support of MultiOBE and FlexConf. Extended file

size dialog with CODESYS > V2.3.9.45.

Support for New Devices Condition Monitoring System (CMS) FM502-CM

New PLC PM590-ARCNET, PM591-2ETH.

New high performance PLC PM595-4ETH-F and PM595-4ETH-M-

XC.

New PROFINET IO device Communication Module CM589-PNIO.

New Ethernet Communication Module CM597-ETH (as replace-

ment for the CM577-ETH module).

Flexible Configuration (FlexConf) Flexible configuration for IO devices connected to local I/O Bus -

handling of multiple hardware configuration files. Feature available

for all PLC except AC500-S Safety CPU.

**SNTP Protocol for AC500-eCo** 

**CPUs** 

Protocol SNTP (Simple Network Time Protocol) for eCo CPUs with

Onboard Ethernet - CPU as time slave.

Function Block Libraries Support for new Function Block BOOTPROJECT HASH INFO (con-

tained in Internal System Library) introduced. This Function Block enables hash checks of all parts of a boot project. Full functionality

are supported from CoDeSys version V2.3.9.45.

**Programming in C-Code** New standard libraries for C-Code editor extended.

Online change are is now available using CoDeSys from

V2.3.9.45.

C++ support on PM590-ETH / PM591-ETH / PM591-2ETH /

PM592-ETH.

IEC60870-5-104 Telecontrol Pro-

tocol

Support of "2nd connection" - multiple substations on one PLC.

Support of "2nd port" for PLCs with Multiple Onboard-Ethernet

(e.g. PM591-2ETH or PM595-4ETH-F/M-XC).