

ABB MEASUREMENT & ANALYTICS | OPERATING INSTRUCTION | OI/FMT700-P/COMPACT-EN REV. D

Sensyflow FMT700-P Compact

Thermal Mass Flowmeter



Compact device with integrated transmitter

Measurement made easy

FMT700-P Compact

Introduction

The Sensyflow FMT700-P Compact is used for the direct mass flow measurement of air.

The measurement is independend of the operating pressure and temperature. It offers top accuracy with short response time. Used in quality assurance, test bench applications, in research and development.

The measuring system is used as a reference system for intake air measurements by leading automotive manufacturers all over the world.

Additional Information

Additional documentation on Sensyflow FMT700-P Compact is available for download free of charge at www.abb.com/flow.

Alternatively simply scan this code:



Table of contents

T	Sarety	
	General information and instructions	3
	Warnings	3
	Intended use	4
	Improper use	4
	Notes on data safety	4
	Warranty provisions	4
	Manufacturer's address	
	Service address	
2	Design and function	5
	Overview	5
	Device description	6
	Measuring principle	6
3	Product identification	7
	Name plate	7
4	Transport and storage	8
	Inspection	8
	Transport	8
	Storing the device	8
	Ambient conditions	8
	Returning devices	8
5	Installation	
	Safety instructions	9
	Installation conditions	9
	Inlet and outlet sections	9
	Ambient conditions	9
	Ambient temperature	9
	Measured medium temperature	
	Operating pressure	
	Installing the sensor	
	Electrical connections	
	Terminal layout	
	Electrical data for inputs and outputs	
	Parameterize	
6	Commissioning	13
•	Checks prior to commissioning	
	Switching on the power supply	
	Inspection after power-up of the power supply	
	Status LED on the transmitter	
	Install the parameterization program	
	Start the parameterization program	
	Parameter descriptions	
	Saving the parameterization	
	Menu bar	
	'Current Device Data' Registration Tab (Start scre	
	'Analog output' Registration Tab	
	'Digital output' Registration Tab	
7	Operation	22
7	-	
	Safety instructions	22

В	Diagnosis / Troubleshooting	22
	General	
	Status LED on the transmitter	
9	Maintenance / Repair	23
	General	
	Calibration interval	23
	Cleaning	23
	Returning devices	
	-	
LO	Dismounting and disposal	24
	Dismounting	
	Disposal	24
11	Accessories	25
	DN 25 components	25
	Components DN 50 to DN 100	
	Components DN 150 to DN 200	
12	Specification	30
13	Additional documents	30
14	Appendix	31
	Return form	

1 Safety

General information and instructions

These instructions are an important part of the product and must be retained for future reference.

Installation, commissioning, and maintenance of the product may only be performed by trained specialist personnel who have been authorized by the plant operator accordingly. The specialist personnel must have read and understood the manual and must comply with its instructions.

For additional information or if specific problems occur that are not discussed in these instructions, contact the manufacturer. The content of these instructions is neither part of nor an amendment to any previous or existing agreement, promise or legal relationship.

Modifications and repairs to the product may only be performed if expressly permitted by these instructions.

Information and symbols on the product must be observed. These may not be removed and must be fully legible at all times. The operating company must strictly observe the applicable national regulations relating to the installation, function testing, repair and maintenance of electrical products.

Warnings

The warnings in these instructions are structured as follows:

▲ DANGER

The signal word '**DANGER**' indicates an imminent danger. Failure to observe this information will result in death or severe injury.

⚠ WARNING

The signal word '**WARNING**' indicates an imminent danger. Failure to observe this information may result in death or severe injury.

CAUTION

The signal word 'CAUTION' indicates an imminent danger. Failure to observe this information may result in minor or moderate injury.

NOTICE

The signal word 'NOTICE' indicates possible material damage.

Note

'**Note**' indicates useful or important information about the product.

... 1 Safety

Intended use

This device is intended for the following uses:

- Direct mass flow measurement of air in open and closed pipelines.
- for indirect measurement of volume flows (through standard density and mass current).

The device has been designed for use exclusively within the technical limit values indicated on the identification plate and in the data sheets.

Improper use

The following are considered to be instances of especially improper use of the device:

- Operation as a flexible compensating adapter in piping, for example for compensating pipe offsets, pipe vibrations, pipe expansions, etc.
- For use as a climbing aid, for example for mounting purposes.
- For use as a bracket for external loads, for example as a support for piping, etc.
- Material application, for example by painting over the housing, name plate or welding/soldering on parts.
- Material removal, for example by spot drilling the housing.

Notes on data safety

This product is designed to be connected to and to communicate information and data via a network interface. It is operator's sole responsibility to provide and continuously ensure a secure connection between the product and your network or any other network (as the case may be). Operator shall establish and maintain any appropriate measures (such as but not limited to the installation of firewalls, application of authentication measures, encryption of data, installation of anti-virus programs, etc.) to protect the product, the network, its system and the interface against any kind of security breaches, unauthorized access, interference, intrusion, leakage and / or theft of data or information.

ABB Automation Products GmbH and its affiliates are not liable

for damages and / or losses related to such security breaches, any unauthorized access, interference, intrusion, leakage and / or theft of data or information.

Warranty provisions

Using the device in a manner that does not fall within the scope of its intended use, disregarding this manual, using underqualified personnel, or making unauthorized alterations releases the manufacturer from liability for any resulting damage. This renders the manufacturer's warranty null and void.

Manufacturer's address

ABB Automation Products GmbH Measurement & Analytics

Schillerstr. 72 32425 Minden Germany

Tel: +49 571 830-0 Fax: +49 571 830-1806

Service address

Customer service center

Tel: +49 180 5 222 580

Email: automation.service@de.abb.com

2 Design and function

Overview



Figure 1: Sensor

Design	Integral mount design
Model	Sensyflow FMT700-P Compact
Measuring media	Air
Measuring accuracy*	\leq ±0.8 % of measured value, repeatability \leq ±0.25 % of measured value
Permissible measuring medium temperature T _{medium}	−25 to 50 °C (−13 to 122 °F)
Permissible operating pressure	0.6 to 2.5 × 102 kPa (2.5 bar abs.)
Flow conditioner	1.5 bar abs.
Process connections	DN 25: Quick-clamping pipe flange, aluminum with quick clamping chains / quick-clamping rings
	DN 50 to 100: Wafer type with raised face
Wetted materials	Anodized aluminum, glass sensor
Power supply	24 V DC, ±10 %
IP rating	in accordance with EN 60529: IP 54
NEMA rating	in accordance with NEMA 12
Communication	serial, V24 / RS232C
Outputs in serial production	
Analog outputs	0 to 5 V DC, 0 to 10 V DC, 0/4 to 20 mA, min. / max. alarm
Digital output	Yes
Pulse / frequency output	Yes
Approvals and certificates	Available on abb.com/flow or on request

^{*} The stated measuring accuracy only applies under the calibration conditions in the stated measuring range.



Figure 2: Aluminum transport box

Note

The sensor is delivered in a robust aluminum transport box. Always use the aluminum transport box to transport the sensor.

... 2 Design and function

Device description



Figure 3: Device design

The Sensyflow FMT700-P Compact works in accordance with the measuring principle of a hot-film anemometer. This measurement method allows for direct measurement of the gas mass flow.

Taking into account the standard density of the air, the standard volume flow can be measured without the need for additional pressure and temperature compensation.

Sensor

The transmitter is integrated in the sensor.

The measuring system comprises two components, a sensor and a measuring section.

The sensor is designed as a meter tube and accommodates the measuring elements and an electronic transmitter circuit. The meter tube is available in six nominal diameters ranging from DN 25 to DN 200 and is installed in the measuring section by using quick-clamping connectors.

Measuring section

The sensor is installed in a measuring section with the help of quick-clamping connectors.

The measuring section itself is made up of sufficiently dimensioned inlet and outlet sections as well as an air filter or flow conditioner.

The flow conditioner can be connected to an air duct, for example, using the connection piece on the suction side. The power supply, output signals and serial interface for the sensor are connected via a connection cable.

The measuring rate is adjustable according to measuring velocity or signal damping requirements.

Measuring principle


Thermal flow metering procedures use different ways to evaluate the flow dependent cooling of a heated resistor as measuring signal.

In a hotfilm anemometer with constant temperature difference control, the heated measurement resistor is maintained at a constant overtemperature in relation to an unheated measurement resistor inside the gas flow.

The heating power required for maintaining the overtemperature depends directly on the flow rate and the material properties of the gas. With a known (and constant) gas composition the mass-flow can be determined by electronically evaluating the heater current / mass-flow curve without additional pressure and temperature compensation.

Together with the standard density of the gas this results

Together with the standard density of the gas this results directly in the standard volume flow. Considering the high measuring range value dynamics up to 1:60, an accuracy smaller than 0.8 % of the measured value is achieved.



- (2) Heating resistor

Figure 4: Measuring principle (simplified)

The gas flows past two temperature-sensitive resistors, measurement resistor and heating resistor, which are part of an electric bridge circuit. Due to the chosen resistance ratio, the heating resistor is heated by the heating current I_H . The measurement resistor adopts the same temperature as the gas. The heating current I_H is preset by the electronic control circuit to produce a constant temperature difference between the heated resistor and the temperature of the gas.

The electric power generated in the heating resistor precisely compensates its loss of heat to the gas flow. As this loss of heat is dependent on the number of particles which collide with the surface of the heating resistor, the heating current I_H represents a measure of the mass flow rate.

Typical applications

Sensyflow FMT700-P Compact for air provide a unique combination of high measuring accuracy, wide measuring range and extremely fast response time. These features especially qualify them for the following application fields in typical load cycling:

- Intake air measurements in combustion engines and fuel cells,
- Test benches for turbo chargers,
- Serial testing of flow dependent components like throttle valves, exhaust fans, air filters, etc.
- · Quality assurance: Reference device for flowmeters,
- · Research and development at universities and institutes.

Notes for ordering

The measuring system consists of the following components, which must be ordered separately:

- 1. Sensor,
- 2. Connection cable for the sensor,
- 3. Measuring section with air filter or flow conditioner,

Note

When using the sensor with modified measuring sections or without measuring sections, influences on measuring accuracy cannot be ruled out.

3 Product identification

Name plate

Note

The name plates displayed are examples. The device identification plates affixed to the device can differ from this representation.




Figure 5: Name plate (example)

4 Transport and storage

Inspection

Check the devices immediately after unpacking for possible damage that may have occurred from improper transport. Details of any damage that has occurred in transit must be recorded on the transport documents.

All claims for damages must be submitted to the shipper without delay and before installation.

Transport



Figure 6: Aluminum transport box

The sensor is delivered in a robust aluminum transport box. Always use the aluminum transport box to transport the sensor.

If the original packaging material is no longer available, wrap the device in bubble wrap or corrugated cardboard and place it in a box of sufficient size lined with a shock-absorbing material (e.g., foam rubber). The thickness of the padding should be appropriate for the device weight and type of shipment. The box must be labeled as "fragile".

For overseas shipment, always add a desiccant (e.g., silica gel) and hermetically seal the device plus desiccant in a layer of polythene that is 0.2 mm thick. Use an amount of desiccant that is appropriate for the packing volume and the expected transport time (at least for three months). You should also line the box with a layer of union paper.

Storing the device

Bear the following points in mind when storing devices:

- Store the device in its original packaging in a dry and dust-free location.
- Observe the permitted ambient conditions for transport and storage.
- · Avoid storing the device in direct sunlight.
- In principle, the devices may be stored for an unlimited period. However, the warranty conditions stipulated in the order confirmation of the supplier apply.

Ambient conditions

Refer to Ambient conditions on page 9.

Returning devices

For the return of devices, follow the instructions in **Returning** devices on page 23.

5 Installation

Safety instructions

WARNING

Risk of injury due to live parts.

Improper work on the electrical connections can result in electric shock.

- Connect the device only with the power supply switched off
- Observe the applicable standards and regulations for the electrical connection.

⚠ WARNING

Risk of injury due to process conditions.

The process conditions, for example high pressures and temperatures, toxic and aggressive measuring media, can give rise to hazards when working on the device.

- Before working on the device, make sure that the process conditions do not pose any hazards.
- If necessary, wear suited personal protective equipment when working on the device.
- Depressurize and empty the device / piping, allow to cool and purge if necessary.

Installation conditions

Inlet and outlet sections

To achieve the provided measuring accuracy, the sensor needs to be installed in the available ABB measuring sections.



Figure 7: Standard measuring sections

The use of an ABB measuring section with an uninterrupted inlet section of $10 \times D^*$ and an outlet section of $5 \times D^*$ in connection with an air filter or flow conditioner complies with the calibration set and ensures measuring accuracy.

Separate components of the measuring sections are also available in the accessory product range.

* D = Piping diameter

Ambient conditions

Storage temperature range

-30 to 85 °C (-22 to 185 °F)

Ambient temperature

-25 to 50 °C (-13 to 122 °F)

Measured medium temperature

-25 to 50 °C (-13 to 122 °F)

IP rating

in accordance with EN 60529: IP 54

NEMA IP rating

in accordance with NEMA 12

EMC compatibility

In accordance with Table 3 DIN EN 61326,1: Use of a device only in a controlled electromagnetic environment.

Vibration

In accordance with IEC 60068-2-6

Shock resistance

In accordance with IEC 60068-2-27

... 5 Installation

Operating pressure

Operating pressure P_{medium} 0.6 to 2.5 × 102 kPa (2.5 bar abs)

Flow conditioner

maximum 1.5 bar abs.

Pressure loss sensor





Figure 8: Pressure loss sensor

Air filter pressure loss (open)



B Mass flow Qm [kg/h]

A Pressure drop dp [hPa]

Figure 9: Air filter pressure loss (open)

Flow conditioner / air filter pressure loss (closed)




Figure 10: Flow conditioner / air filter pressure loss (closed)

Installing the sensor

Before installing the sensor, observe the following points:

- The ambient conditions at the installation site comply with the requirements in **Ambient conditions** on page 9.
- The operating pressure complies with the requirements in **Operating pressure** on page 10

Install the sensor:

 Install the sensor in the measuring section. Make sure that the tapered flange connection is secure (tightness) and observe the flow direction (direction indicated by arrow).




Figure 11: Flow direction

2. Establish the electrical connection in accordance with the requirements **Electrical connections** on page 11.

Note

For available components to set up the measuring section see **Accessories**

on page 25.

Electrical connections

Terminal layout

Please use the supplied cable for the electrical connection of the flowmeter sensor. It is connected to the measuring device using the plug.

Only 24 VDC supply voltage should be used.




Figure 12: Electrical connection

Pin	Color	Function / comments
1	White	Analog output, signal (+)
2	Brown	RS 232C TxD – transmi data
3	Green	Pulse / frequency output, signal (+)
4	Yellow	Power supply +24 V DC
5	Gray	Power supply GND
6	Pink	RS 232C RxD – receive data
7	Blue	Analog output, GND
8	Red	Pulse / frequency output + RS 232C, GND
Shield	_	Functional earth

Note

Insulate any unused wire ends.

Electrical data for inputs and outputs

Power supply

Integral mount design		
Pin / color	4+ (yellow) / 5- (gray)	
Operating voltage	24 V DC (±10 %)	
Input Current	Peak < 1 A; operation < 0.6 A	
Fuse	At least 2 A slow-blow	
Power consumption	< 15 W	

Analog output

Can be optionally configured as current output (0 (4) to 20 mA) or voltage output (0 to 10 (5) V).

Current output	active*
Pin / color	1+ (white) / 7- (blue)
Output signal	0 (4) to 20 mA
Signal in the event of an	< 3.5 mA or > 22 mA
error	
Load R _B	< 500 Ω

Voltage output	Active
Pin / color	1+ (white) / 7- (blue)
Output signal	0 to 10 (5) V
Signal in the event of an	Min. or max.
error	
Input Current	< 1 mA

* When selecting the current output 0 (4) to 20 mA, the analog output supplies an active signal. The device delivers the current independently without external power supply.

... 5 Installation

... Electrical connections

Digital output

Can be configured as pulse / frequency outputs or binary outputs.




Figure 13: Connection example

The digital output offers a 24 V HIGH signal or a 0 V LOW signal. The output can be wired as active or passive.

Digital output (pas	sive)
Pin / color	3+ (green) / 8- (red)
U _{max}	24 V DC
I _{max}	-20 mA
f _{max}	2500 Hz

The output current must be limited to -20 mA in LOW state to guarantee an output voltage $\rm U_a$ < 2.5 V.

te

The output current must be limited to 1 mA in HIGH state to guarantee an output voltage $\rm U_a > 15~\rm V.$

Communication

RS 232	
Pin / color	TxD: 2 (brown) / RxD: 6 (pink) / GND: 8- (red)
Baud rate	9600 bits/sec.
Stop bits	1
Parity	None
Data bits	8

Parameterize

The Sensyflow FMT700-P Compact can simultaneously operate one analog output (current 0 / 4 to 20 mA or voltage 0 to 5 / 10 V), one digital output (frequency, pulse, alarm) and a serial RS 232 interface.

Parameterization of the measuring system can also take place via the serial interface. Using a PC or laptop, you can change the output signal used or the adjust the settings of the measuring ranges and signals.

The parameterization program is included in the standard scope of delivery.

For easier connection of the Sensyflow FMT700-P Compact in the test field, a D - SUB female connector and a USB 2.0, serial adapter including USB cable is supplied.

D - SUB female connector




Figure 14: Female connector

Electrical connection D - SUB female connector

Wire color	Terminal no. on the	Signal
connection cable	female connector	
Brown	2	RS 232 / TxD
Pink	3	RS 232 / RxD
Red	5	RS 232 / GND

USB 2.0, serial adapter



Figure 15: Adapter

6 Commissioning

Checks prior to commissioning

The following points must be checked before commissioning the device:

- Correct wiring in accordance with Electrical connections on page 11.
- The ambient conditions must comply with the requirements in Ambient conditions on page 9.
- The power supply must meet the requirements set out on the name plate.

Switching on the power supply

- 1. Switch on the power supply.
 - The status LED blinks red during the initialization phase (approx. 30 s).
 - After the initialization phase, the status LED lights up in a continuous green color.
- 2. Perform parameterization of the flowmeter (see **Parameter descriptions** on page 14).

The flowmeter is now ready for operation.

Inspection after power-up of the power supply

The following points must be checked after commissioning the device:

Parameter configuration must correspond to the operating conditions.

Status LED on the transmitter

The status LED on the transmitter indicates the operating condition of the device and displays possible faults.

LED	Description
Continuous green light	The sensor is ready for operation.
Green flashing	The measuring range set has been up-scaled.
Continuous red light	Parameter or hardware fault on the sensor. Reestablish parameterization, see Reestablish the parameterization on page 14. Repairs required, contact ABB Service.
Red blinking	Initialization phase of the device. (approx. 30 s after power-up of the power supply or after parameter changes)
Red slowly blinking	Undervoltage. Check the supply power
Red quickly blinking	EEPROM fault. Repairs required, contact ABB Service.

Install the parameterization program

The parameterization program is located on the provided USB stick.


The parameterization program must be installed on a PC / laptop:

- 1. Insert the USB stick into the PC / laptop.
- 2. Open the USB stick in Explorer.
- 3. Launch the 'SETUP.EXE' file with administrator rights.
- 4. Follow the instructions in the installation program. Change the preset installation directory as needed.
- 5. Select the desired language (German, English or French). The language can be changed in the parameterization program only.

... 6 Commissioning

Start the parameterization program

- Connect the sensor to an open RS232 interface of the PC / laptop using the D-Sub adapter. If no RS232 interface is available, additionally use the USB-RS232 adapter.
- 2. Power-up the power supply of the sensor.
- 3. To launch the parameterization program, execute the 'P_Compact_V100.exe' file in the installation directory.
- The COM 1 interface is used by default. If another interface is used, select it in the 'Connection' menu.



- Confirm the selected interface by pressing 'OK'. If no connection can be established, an error message will appear. In this case, check the following points:
 - Check the interface connection with the PC / laptop.
 - Is the sensor ready for operation?
 (Is the status LED on the sensor continuous green)
 - Has the correct interface been selected.
- If the interface connection has been successfully established, the starting screen of the parameterization program is displayed (see 'Current Device Data' Registration Tab (Start screen) on page 16).

Parameter descriptions

NOTICE

Data loss

Data loss due to the shut-off of power supply during the initialization phase (status LED blinks red) of the device.

 Do not switch off the power supply until the device is ready for operation(status LED is continuous green).

Saving the parameterization

If any parameterization has been changed in the parameterization program and transferred to the device through the 'Accept' button, a save / initialization phase of the device follows and the status LED blinks red.

 The supply voltage must not be switched off until the status LED is continuous green once more.

The modified parameters will not be saved properly if this rule is not obeyed.

After the repeated power-up of the device, a data inconsistency will be detected during the initialization phase, the status LED will switch to continuous red and the device will no longer function correctly.

Reestablish the parameterization

Once the status LED is continuous red, communication with the parameterization software can be resumed.

- 1. The parameterization data must be resaved by selecting the 'Accept' button.
 - Wait until the symbol indicating that a program is running disappears and the status indication for the 'initialization phase' is terminated.
 - · The status LED is still continuous red at this stage.
- 2. Perform a hardware reset by powering down and powering up the power supply.
 - After the initialization phase, the status LED is continuous green and the device is ready for operation.

Note

If operation readiness cannot be reestablished, contact ABB Service.

Menu bar

Menu / parameter	Description				
Configuration	•				
Factory settings	Shows the parameters set at the factory				
Savings	Saves the current parameter set to a data storage medium.				
Load	Loads a saved parameter set from a data storage medium.				
Delete	Deletes a saved parameter set from a data storage medium.				
Print	Prints the current parameter set to the configured standard printer.				
Select Language	Select the program language: German, English, French				
Select unit	Select the flow unit from a unit list.				
Insert / delete unit	Create / delete a new unit.				
	Refer to Add user-defined unit on page 15.				
Exit	Exits the parameterization program.				
Connection					
Connection	Select the serial interface for connection with the				
	sensor.				
Data backup					
Data backup	Save the changed data to the device				

Add user-defined unit




Figure 16: 'Add unit' menu


A user-defined unit can be created here. The unit must have the possibility of being presented as a multiple of kg/h.

Parameter	Description				
Unit	Name of the unit (text field).				
Factor	Enter the factor of the unit in kg/h. Decimal number must be entered using a period rather than a comm				
Standard condition	Enter the standard state to which the unit makes reference. Example: 0 °C, 1013mbar				
Gas type	Enter the gas type for the unit (text field).				
Available units	Display the available units.				
Cancel	Cancel the entry.				
Savings	Save the new unit.				
Delete unit	Delete units				

... 6 Commissioning

... Parameter descriptions

'Current Device Data' Registration Tab (Start screen)



- 1 Menu bar
- (2) Registration Tab
- (3) Device identification
- (4) Current measured value
- (5) Standard condition parameter display (when selecting a volume unit)
- Figure 17: Parameterization program, 'Current Device Data' Registration Tab
- 6 Status bar
- 7 Sensor connection status
- (8) Analog output parameter display
- 9 Digital output parameter display (only if configured)

Device detection

Display information on the connected sensor.

Parameter	Description		
Production number	Unique serial number of the connected sensor, please		
	provide this number with any inquiry to ABB.		
Version	Sensor firmware software version.		

Measured value




Figure 18: 'Measured value' field

In the measured value area, the current measured value is displayed in % as a bar graph.

If the digital output of the sensor is configured as a switch output (see 'Switch output' option on page 21), the graph displays the up-scale or down-scale of the set limit value:

- If the current measured value down-scales the set lower limit, the bar has a **blue** color.
- If the current measured value up-scales the set upper limit, the bar has a red color.
- If the current measured value is within the set limits, the bar has a **green** color.

Standard condition



Figure 19: Standard condition field

When a volume unit is selected (e.g. Nm³/h), the unit always makes reference to a defined standard condition. In the standard condition field, the absolute pressure and reference temperature for the selected volume unit is displayed. When a mass flow unit is selected (e.g. kg/h) the field remains empty.

Status bar

Display of information and help texts for the current action. In addition, the current date and time are displayed.

Digital output

Display of the digital output configuration.

Frequency output option:




Figure 20: Frequency option

The current measured value is output as a frequency on the digital output.

Parameter	Description			
Frequency [min]	Frequency in Hz for '0' flow.			
Frequency [max]	Frequency in Hz for the set upper range value.			

... 6 Commissioning

... Parameter descriptions

Impulse output option:



Figure 21: Impulse output

The current measured value is output in impulses/unit on the digital output.

Parameter	Description				
Value	Set flow rate per impulse.				
Duration	Set impulse length.				
Polarity	Set polarity (low/high) for the impulse.				

Switch option:





Figure 22: Switch

The current measured value is monitored for fluctuation either side of an adjustable limit value.

The polarity gives the condition of the signal within the set limits.

Parameter	Description
Threshold min	Set lower limit value.
Threshold max	Set upper limit value.
Polarity	Set polarity (low/high).

'Analog output' Registration Tab



- (1) 'Configure' area, selection of the parameters to be configured via check box ☑ / □.
- 3 Display of the newly selected values

(2) Display of the currently set values

Figure 23: Parameterization program, 'Analog Output' Registration Tab

This tab is used to configure the analog output. For the sake of transparency, both the current and amended values are displayed at the same time.

- The parameters to be changed should be selected using the check box oxdot and the values changed in the entry field.
- The changed values are saved to the sensor using the 'Accept' button.

 The sensor is restarted and initialized (LED on the transmitter blinks red). No measured values are displayed during initialization.

Parameter for the analog output

Parameter	Description					
Analog output	Select the operating mode for the analog output: 0-20 mA, 4-20 mA, 0-5 V, 0-10 V					
Upper range value	Set the flow rate for the maximum current / maximum voltage on the analog output.					
Low flow	Set the flow rate below which no measurement is made (measured value = 0 %)					
Filter factor	Set the time constant for the damping of the output signal in ms.					
Output in the event of an error	Select the output behavior in the event of an error.					
	Min: Analog output 0 %					
	Max: Analog output 100 %					
	• Up: Analog output > 22.5 mA*					
	Down: Analog output < 3.5 mA* **					


 $^{^{*}}$ not for operating mode 0-5 V, 0-10 V

^{**} not for operating mode 0-20 mA

... 6 Commissioning

... Parameter descriptions

'Digital output' Registration Tab



- 'Configure' area, selection of the parameters to be configured via check box ☑ / □.
- 3 Display of the newly selected values

2 Display of the currently set values

Figure 24: Parameterization program, 'Digital Output' Registration Tab

This tab is used to configure the digital output. For the sake of transparency, both the current and amended values are displayed at the same time.

- The parameters to be changed should be selected using the check box \square and the values changed in the entry field.
- The changed values are saved to the sensor using the 'Accept' button.
 The sensor is restarted and initialized (status LED on the transmitter blinks red). No measured values are displayed during initialization.

Digital output

Configuration of the digital output.

'Standard Frequency' option




Figure 25: Standard Frequency output

In the **'Standard Frequency'** operating mode, you can switch between two frequency ranges **1 to 100 Hz** or **10 to 1000 Hz**. The lower frequency corresponds to a flow rate of 0 %, while the upper frequency corresponds to a flow rate of 100 % of the set upper range value.

'Variable Frequency' option




Figure 26: Variable Frequency output

In the 'Variable Frequency' operating mode, you can enter any lower and upper frequency.

The lower frequency corresponds to a flow rate of 0 %, while the upper frequency corresponds to a flow rate of 100 % of the set upper range value.

Parameter	Description				
min	Enter the frequency for 0 % flow rate				
max	Enter the frequency for 100 % flow rate, maximum				
	2500 Hz				

'Impulse output' option



Figure 27: Impulse output

The current measured value is output in impulses/unit on the digital output.

Parameter	Description				
Value	Enter the flow rate per impulse.				
Duration	Set the impulse length.				
Polarity	Select polarity (low/high) for the impulse.				

'Switch output' option



Figure 28: Switch output

The current measured value is monitored for fluctuation either side of an adjustable limit value.

The polarity gives the condition of the signal within the set limits.

Parameter	Description			
Lower threshold	Enter the lower limit value.			
Upper threshold	Enter the upper limit value.			
Polarity	Select polarity (low/high).			

'No output' option

Deactivates the digital output.

7 Operation

Note

The device does not have operating elements for parameterization on site.

Operation and configuration is performed through the parameterization program, see **Parameter descriptions** on page 14.

Safety instructions

If there is a chance that safe operation is no longer possible, take the device out of operation and secure it against unintended startup.

8 Diagnosis / Troubleshooting

General

Error messages and device disruptions are indicated via the status LED on the sensor.

Status LED on the transmitter

The status LED on the transmitter indicates the operating condition of the device and displays possible faults.

LED	Description The sensor is ready for operation.				
Continuous green light					
Green flashing	The measuring range set has been up-scaled.				
Continuous red light	 Parameter or hardware fault on the sensor. Reestablish parameterization, see Reestablish the parameterization on page 14. Repairs required, contact ABB Service. 				
Red blinking	Initialization phase of the device. (approx. 30 s after power-up of the power supply or after parameter changes)				
Red slowly blinking	Undervoltage. Check the supply power				
Red quickly blinking	EEPROM fault. Repairs required, contact ABB Service.				

9 Maintenance / Repair

General

All measuring systems are calibrated using in-house calibration equipment. The device does not require any maintenance.

Occasional cleaning may be required where the air contains large amounts of dust or oil.

We recommend connecting an upstream air filter for this type of application.

Filters guaranteeing air quality in accordance with ISO 8573.1: Class 1-2 have proven especially useful here.

Calibration interval

Note

Due to the various conditions of use of our measuring devices, no general calibration interval can be defined.

The more the conditions of use differ from the reference conditions or the device is operated beyond typical load cycling at the upper measuring range limit in continuous operation, the shorter the calibration and maintenance intervals become. For typical operation, we recommend that you inspect our measuring devices after one year. Depending on the result, future calibration intervals can be shortened or lengthened.

Cleaning

Cleaning the flowmeter sensor will only remove particles; sticky or stubborn stains cannot be removed.

If the sensor becomes contaminated with oil or deposits which cannot be blown out using air, the sensor needs to be returned to the manufacturer for cleaning in a special solution.

This will also involve a complete recalibration process.

NOTICE

Damage to the sensor

Damage to the sensor due to improper handling and cleaning. Under no circumstances should components like the honeycomb or sieve be removed from the flowmeter sensor, nor should they be bent or damaged in any other way.

 Any attempts to clean the sensor that go beyond the steps described above may cause destruction to the sensor.

Cleaning through blow-out:

- Remove the connector of the connection cable from the sensor.
- 2. Make sure the pipeline is depressurized.
- 3. Remove the transmitter from the measuring section.
- 4. Carefully blow-out the sensor using clean pressurized air.
 - If the impurities cannot be removed, send the sensor to the manufacturer for cleaning and calibration.
- 5. Install the transmitter in the measuring section.
- 6. Reconnect the connection cable to the sensor.

Returning devices

Use the original packaging or a secure transport container of an appropriate type if you need to return the device for repair or recalibration purposes.

Fill out the return form (see **Return form** on page 31) and include this with the device.

In accordance with the EU Directive governing hazardous materials, the owner of hazardous waste is responsible for its disposal or must observe the following regulations for shipping purposes:

All devices delivered to ABB must be free from any hazardous materials (acids, alkalis, solvents, etc.).

Please contact Customer Center Service acc. to page 4 for nearest service location.

10 Dismounting and disposal

Dismounting

⚠ WARNING

Risk of injury due to process conditions.

The process conditions, for example high pressures and temperatures, toxic and aggressive measuring media, can give rise to hazards when dismantling the device.

- If necessary, wear suited personal protective equipment during disassembly.
- Before disassembly, make sure that the process conditions do not pose any safety risks.
- Depressurize and empty the device / piping, allow to cool and purge if necessary.

Bear the following points in mind when dismantling the device:

- · Switch off the power supply.
- Disconnect electrical connections.
- Allow the device / piping to cool and depressurize and empty. Collect any escaping medium and dispose of it in accordance with environmental guidelines.
- Use suited tools to disassemble the device, taking the weight of the device into consideration.
- If the device is to be used at another location, the device should preferably be packaged in its original packing so that it cannot be damaged.
- Observe the notices in **Returning devices** on page 23.

Disposal

Note



Products that are marked with the adjacent symbol may **not** be disposed of as unsorted municipal waste (domestic waste).

They should be disposed of through separate collection of electric and electronic devices.

This product and its packaging are manufactured from materials that can be recycled by specialist recycling companies.

Bear the following points in mind when disposing of them:


- As of 8/15/2018, this product will be under the open scope of the WEEE Directive 2012/19/EU and relevant national laws (for example, ElektroG - Electrical Equipment Act - in Germany).
- The product must be supplied to a specialist recycling company. Do not use municipal waste collection points.
 These may be used for privately used products only in accordance with WEEE Directive 2012/19/EU.
- If there is no possibility to dispose of the old equipment properly, our Service can take care of its pick-up and disposal for a fee.


11 Accessories

DN 25 components

All dimensions specified in mm (in). The numbers (e.g. [1]) of the components correspond to the markings on the in the ordering information, see Ordering information in the data sheet.

KF = ISO-KF flange (ISO small flange) / ZWF = wafer type (with raised face)





Measuring section 3

(including flow conditioner, closed filter)

Alternative measuring section 1

(concealed shown with a dashed line, including open filter, filter cartridge only)

Including the required flanges and clamping rings / clamping chains





Figure 1: Component dimensions DN 25							
DN	Ø D	Ø D2	Ø D3	Ø D4	Ø D6	Ø D7	Ø Di
25	32 (1.26)	26.1 (1.03)	30 (1.18)	27 (1.06)	Approx. 150 (5.91)	78 (3.07)	24 (0.94)

... 11 Accessories

... DN 25 components



[6][11]/[12][6] Sectional detail pipe connection (without clamping ring) Ø 24 (0.94) Ø 27 (1.06) 10 10

(0.39)

4 (0.16)

(0.39)






Figure 2: Accessory dimensions DN 25

Components DN 50 to DN 100

All dimensions specified in mm (in). The numbers (e.g. [1]) of the components correspond to the markings on the in the ordering information, see Ordering information in the data sheet.

KOF = Tapered flange (with raised face and groove for O-ring) / ZWF = Wafer type (with recessed face)





Measuring section 3

(including flow conditioner, closed filter)

Alternative measuring section 1

(concealed shown with a dashed line, including open filter, filter cartridge only)

Including the required flanges and clamping rings / clamping chains

Standard measuring section




Figure 3: Component dimensions DN 50 to DN 100


DN	L1	L2	L3	L4	L5	L6	L7	L8	L9
50	Approx. 356	506 (19.92)	256 (10.08)	50 (1.97)	Approx. 660	504 (19.84)	254 (10.00)	Approx. 1600	184 (7.24)
	(14.02)				(25.98)			(62.99)	
80	Approx. 401	806 (31.73)	406 (15.98)	80 (3.15)	Approx. 740	804 (31.65)	404 (15.91)	Approx. 2140	189 (7.44)
	(15.79)				(29.13)			(84.25)	
100	Approx. 526	1006 (39.61)	506 (19.92)	100 (3.94)	Approx. 840	1004 (39.53)	504 (19.84)	Approx. 2610	254 (10.00)
	(20.71)				(33.07)			(102.76)	

DN	Ø D	Ø D2	Ø D3	Ø D4	Ø D5	Ø D6	Ø D7	Ø Di
50	66 (2.60)	64 (2.52)	70 (2.76)	60 (2.36) Ap	prox. 150 (5.91)	Approx. 200 (7.87)	78 (3.07)	58 (2.28)
80	91 (3.58)	89 (3.50)	95 (3.74)	85 (3.35) Ap	orox. 200 (7.87)	Approx. 250 (9.84)	98 (3.86)	80 (3.15)
100	119 (4.69)	118 (4.65)	122 (4.80)	114 (4.49) App	orox. 240 (9.45) A	Approx. 300 (11.81)	148 (5.83)	110 (4.33)


... 11 Accessories

... Components DN 50 to DN 100

KOF = Tapered flange (with raised face and groove for O-ring) / ZWF = Wafer type (with recessed face)



[10][12][11]
Sectional detail pipe connection (without clamping ring)






Figure 4: Accessory dimensions DN 50 to DN 100

DN	L1	L2	L9	Ø D2	Ø Di
50	102 (4.02)	72 (2.83)	184 (7.24)	64 (2.52)	58 (2.28)
80	145 (5.71)	114 (4.49)	189 (7.44)	89 (3.50)	80 (3.15)
100	158 (6.22)	127 (5.00)	254 (10.00)	118 (4.65)	110 (4.33)


Components DN 150 to DN 200

All dimensions specified in mm (in). The numbers (e.g. [1]) of the components correspond to the markings on the in the ordering information, see Ordering information in the data sheet.

KF = Tapered flange (with raised face and groove for O-ring) / ZWF = Wafer type (with recessed face)

10 (0.39)

4 (0.16)



Measuring section 3

(including flow conditioner, closed filter)

Alternative measuring section 1

(concealed shown with a dashed line, including open filter, filter cartridge only)

Including the required flanges and clamping rings / clamping chains

L8 L5 L2 [7]

Standard measuring section

4 (0.16)

L9 L7 [5] [2]

KOF

ZWF

ZWF

KOF

4 (0.16)

10 (0.39)

Figure 5: Component dimensions DN 150 to DN 200

DN	L1	L2	L3	L4	L5	L6	L7	L8	L9
150	Approx. 513	1518 (59.76)	768 (30.24)	159 (6.26)	Approx. 900	1509 (59.41)	759 (29.88)	Approx. 3460	280 (11.02)
	(20.20)				(35.43)			(136.22)	
200	Approx. 513	2018 (79.49)	1018 (40.08)	159 (6.26)	Approx. 850	2009 (79.09)	1018 (40.08)	Approx. 4220	330 (12.99)
	(20.20)				(33.46)			(166.14)	


KOF ZWF

DN	ØD	Ø D2	Ø D4	Ø D5	Ø D6	Ø D7	Ø Di
150	151 (5.94)	158 (6.22)	153 (6.02)	Approx. 300 (11.81)	Approx. 355 (13.98)	198 (7.80)	149 (5.87)
200	201,5 (7.93)	205 (8.07)	204 (8.03)	Approx. 300 (11.81)	Approx. 355 (13.98)	248 (9.76)	199 (7.83)


... 11 Accessories

... Components DN 150 to DN 200

KOF = Tapered flange (with raised face and groove for O-ring) / ZWF = Wafer type (with recessed face)



[10][12][11]
Sectional detail pipe connection
(without clamping ring)






Figure 6: Accessory dimensions DN 150 to DN 200

DN	L1	L2	L9	Ø D2	Ø Di
150	Approx. 220 (8.66)	280 (11.02)	151 (5.94)	149 (5.87)	Approx. 220 (8.66)
200	Approx. 280 (11.02)	330 (12.99)	202 (7.95)	200 (7.87)	Approx. 280 (11.02)

12 Specification

Note

The device data sheet is available in the ABB download area at www.abb.com/flow.

13 Additional documents

Note

All documentation, declarations of conformity, and certificates are available in ABB's download area.

www.abb.com/flow

14 Appendix

Return form

Statement on the contamination of devices and components

Repair and/or maintenance work will only be performed on devices and components if a statement form has been completed and submitted.

Otherwise, the device/component returned may be rejected. This statement form may only be completed and signed by authorized specialist personnel employed by the operator.

Customer details:		
Company:		
Address:		
Contact person:	Telephone:	
Fax:	Email:	
Device details:		
Type:		Serial no.:
Reason for the return/desc	cription of the defect:	
	njunction with substances which pose a threat or ris	sk to health?
☐ Yes ☐ N		
If yes, which type of contan	nination (please place an X next to the applicable iten	ns):
biological	☐ corrosive / irritating	combustible (highly / extremely combustible)
☐ toxic	<pre>explosive</pre>	other toxic substances
☐ radioactive		
Which cubetances have con	me into contact with the device?	
1.	The lifto contact with the device:	
2.		
3.		
3.		
We hereby state that the de	evices/components shipped have been cleaned and a	are free from any dangerous or poisonous substances.
Town/city, date	Signa	ature and company stamp



_

ABB Measurement & Analytics

For your local ABB contact, visit:

www.abb.com/contacts

For more product information, visit:

www.abb.com/flow

We reserve the right to make technical changes or modify the contents of this document without prior notice. With regard to purchase orders, the agreed particulars shall prevail. ABB does not accept any responsibility whatsoever for potential errors or possible lack of information in this document.

We reserve all rights in this document and in the subject matter and illustrations contained therein. Any reproduction, disclosure to third parties or utilization of its contents – in whole or in parts – is forbidden without prior written consent of ABB.