Release Notes
AC500 CPU Firmware

ABB Automation Products GmbH

Wallstadter Str. 59

68526 Ladenburg, Germany

Telephone: +49 62 21 701 1444

Fax: +49 62 21 701 1382

Email: plc.sales@de.abb.com

Internet: www.abb.com/plc

Improvements in Firmware V2.7.0

EtherCAT:

Datatypes REAL and LREAL are not supported in IO configuration of EtherCAT devices. - **Fixed**

CANopen/CAN:

CM598-CN CAN2A/2B: PLC can crash, when CAN frames with a data length less than 8 bytes are received. - **Fixed**

Ethernet:

Communication error when more than 49 sockets are created on PM591-2ETH via SysLibSockets. - **Fixed**

New features in Firmware V2.7.0

New devices

Support of new Safety PLC SM560-S-FD-1
Support of new Safety PLC SM560-S-FD-4

CM589-PNIO-x, PROFINET IO Device communication module for Safety

CM589-PNIO-1: support of safety data
CM589-PNIO-4: support of safety data