Technote: **technote_160428_AW6.03**

Title:

Product Type:	**IRC5 RW 6.x**
Year Model:	**M2004**
Keywords:	**IRC5 RW 6**
Author:	**Anders Trillkott**
Revision:	**-**

_____

Due to an internal license check error a customer with a single arc system "633-4 Arc" cannot upgrade to RobotWare version 6.03 if option "623-1 Multitasking" isn't present.

Installation will fail within Installation Manager saying there is a missing dependency option but not explaining what dependency that is missing.

The problem is solved in RobotWare 6.03.01.

If a customer needs to upgrade to 6.03 they must contact ABB Robotics After Sales to get a new license file that contains "623-1 Multitasking". Customers that have "633-4 Arc with MultiProcess" are not affected.

Recommendation is to wait for the 6.03.01 release