IECEx Quality Assessment Report Summary

INTERNATIONAL ELECTROTECHNICAL COMMISSION
IEC Certification System for Explosive Atmospheres

for rules and details of the IECEx Scheme visit www.iecex.com

QAR Ref. No.: **FR/LCI/QAR08.0003/15**

QAR Free Ref. No.: **15064528-778848/778849/778850**

Status:**Issued**

Details of change: Renewal

Date of issue:**2022-11-28**

Audit FIMOT : 2022-09-26
Audit DELCE : 2022-09-27
Audit FIMOT : 2022-09-28&29

Valid until:**2025-11-21**

Audit date:**2022-09-29**

Site(s) audited:

ABB Logistics Center Europe GmbH
Braukerweg 132
58706 Menden
Germany

ABB Oy, IEC LV Motors
Strömbergin Puistotie 5A
Vaasa FI 65320
Finland

ABB Sp.zo.o
Ul. Placydowska
95-070 Aleksandrow Lodzki
Poland

Issuing ExCB: **LCIE - Laboratoire Central des Industries Electriques (LCIE)**

Manufacturer:

ABB Oy, IEC LV Motors
Strömbergin puistotie 5A
FI 65320 Vaasa,

Location of Manufacturer: **Finland**

Product information: Ex asynchronous motors and Generators

Protection concept: **'d', 'de', 'ec', 'nA', 'tb', 'tc'**

Related QARs:

FR/LCI/QAR08.0003/00
FR/LCI/QAR08.0003/01
FR/LCI/QAR08.0003/02
FR/LCI/QAR08.0003/03
FR/LCI/QAR08.0003/04
FR/LCI/QAR08.0003/05
FR/LCI/QAR08.0003/06
FR/LCI/QAR08.0003/07
FR/LCI/QAR08.0003/08
FR/LCI/QAR08.0003/09
FR/LCI/QAR08.0003/10
FR/LCI/QAR08.0003/11
FR/LCI/QAR08.0003/12
FR/LCI/QAR08.0003/13
FR/LCI/QAR08.0003/14

IECEx Quality Assessment Report Summary

Related Certificates (manual insertion)::

IECEx LCI 04.0004 issue: 0
IECEx LCI 04.0005 issue: 0
IECEx LCI 04.0005X issue: 1
IECEx LCI 04.0006 issue: 0
IECEx LCI 04.0006X issue: 1
IECEx LCI 04.0007 issue: 0
IECEx LCI 04.0007X issue: 1
IECEx LCI 04.0008 issue: 0
IECEx LCI 04.0008X issue: 1
IECEx LCI 04.0009 issue: 0
IECEx LCI 04.0009X issue: 1
IECEx LCI 04.0010 issue: 0
IECEx LCI 04.0011 issue: 0
IECEx LCI 04.0011X issue: 1
IECEx LCI 04.0011X issue: 2
IECEx LCI 04.0011X issue: 3
IECEx LCI 04.0012 issue: 0
IECEx LCI 04.0012X issue: 1
IECEx LCI 04.0029 issue: 0
IECEx LCI 04.0029X issue: 1
IECEx LCI 04.0030 issue: 0
IECEx LCI 04.0030X issue: 1
IECEx LCI 04.0031 issue: 0
IECEx LCI 04.0031X issue: 1
IECEx LCI 04.0032 issue: 0
IECEx LCI 04.0032X issue: 1

Related Certificates (automatic linking)::

Related Certificates for previous versions:

IECEx CML 20.0039U issue: 0
IECEx CML 20.0040U issue: 0
IECEx EESF 20.0036X issue: 0
IECEx LCI 07.0001X issue: 3
IECEx LCI 09.0008X issue: 4
IECEx LCI 09.0009X issue: 4
IECEx LCI 11.0023X issue: 0
IECEx LCIE 13.0047X issue: 1
IECEx LCIE 19.0038X issue: 0
IECEx LCIE 19.0039X issue: 1
IECEx LCIE 19.0042X issue: 0
IECEx UL 18.0081X issue: 1
IECEx UL 20.0026X issue: 0
IECEx UL 20.0026X issue: 3
IECEx VTT 12.0010X issue: 2
IECEx VTT 13.0017X issue: 3
IECEx CML 20.0039U issue: 1
IECEx CML 20.0040U issue: 1
IECEx LCI 07.0001 issue: 1
IECEx LCI 09.0008X issue: 2
IECEx LCI 09.0009X issue: 2
IECEx LCI 09.0012X issue: 1
IECEx LCI 11.0023X issue: 1
IECEx LCIE 19.0036X issue: 0
IECEx LCIE 19.0038X issue: 1
IECEx LCIE 19.0041X issue: 0
IECEx LCIE 19.0042X issue: 1
IECEx UL 18.0081X issue: 2
IECEx UL 20.0026X issue: 1
IECEx VTT 12.0010X issue: 0
IECEx VTT 13.0017X issue: 1
IECEx VTT 14.0012X issue: 0
IECEx CML 20.0039U issue: 2
IECEx CML 20.0040U issue: 2
IECEx LCI 07.0001X issue: 2
IECEx LCI 09.0008X issue: 3
IECEx LCI 09.0009X issue: 3
IECEx LCI 09.0012X issue: 2
IECEx LCIE 13.0047X issue: 0
IECEx LCIE 19.0036X issue: 1
IECEx LCIE 19.0039X issue: 0
IECEx LCIE 19.0041X issue: 1
IECEx UL 18.0081X issue: 0
IECEx UL 19.0069X issue: 0
IECEx UL 20.0026X issue: 2
IECEx VTT 12.0010X issue: 1
IECEx VTT 13.0017X issue: 2

Comments: Production Quality Assurance Notification under directive 2014/34/EU : LCIE 01 ATEX Q 8013

Modification of ABB Oy, IEC LV Motors adress.