



Release Notes PS501 V2.0.1 (Update for PS501 V2.0.0)

ABB STOTZ-KONTAKT GmbH, Eppelheimer Straße 82, 69123 Heidelberg,
<http://www.abb.de/stotz-kontakt>

Please read the following information carefully before performing the Update!

Bugfixes and changes:

- A) bugfixes:
 - a. Compile issue on using the libraries Counter_AC500_V11.lib and HA_CS31_AC500_V13.lib or HA_CS31_AC500_V20.lib in the same project
 - b. standard language: taken from operating system settings
 - c. fixed issues in the configuration of
 - i. EtherCAT
 - ii. Profibus
 - iii. PROFINET
- B) Changed naming from „ABB Configurator“ to „Control Builder Plus“

Prerequisites:

- ABB PS501 V2.0.0 installed

Installation instructions:

- Close all applications
- Run Update.exe and follow the instructions on the screen