

Force Measurement service center Västerås, Sweden




ABB Force Measurement service center in Västerås, Sweden has the capability to do tests, inspections and repairs for all customers independent of location but with focus on European, African, Indian and Middle East customers. The service center offers a broad range of repair services of all Force Measurement products and is equipped with the latest technology to ensure high quality inspections, tests and repairs.

ABB Force Measurement service center strictly follows established repair and faultfinding procedures, starting with visual inspection, cleaning, detailed inspection and diagnostic measurements. Continuing with the actual repair work and ending with functional tests.

All items repaired are upgraded to the latest versions, as specified by our product management, unless otherwise instructed by customers.

In everything we do, we aim at the fastest turnaround times possible. For the majority of repairs we are able to promise a repair with predefined lead time so you as customer can plan for the repair. Every repair we do is accompanied by a report, detailing the faults found and the remedies taken.



Stressometer measuring rolls	Västerås, Sweden
Basic repair	X
Complete repair	X
Revamp	X
Balancing of roll	X
Repair of journals	X
Exchange of rings	X
Exchange of single zones transducers	X
Cleaning and repairs on-site	X
Rental of ring heater	X
DTU PFSA 107	
Exchange DTU	X
STU PFSA 103	
Test/cleaning	X
Repair	X
Revamp	X
Exchange STU	X
Schleifring slipping	
Test/cleaning	X
Repair	X
Revamp	X

For more information please contact:

ABB AB
Measurement & Analytics
Force Measurement service center
 S-721 59 Västerås, Sweden
 Phone: +46 21 32 50 00

www.abb.com/measurement

Load cells, sensors and gauges	Västerås, Sweden
Roll force load cells	
Inspection and test	X
Recalibration, PFVL 141 only	X
Revamp	X
Fast repair	X
Strip tension load cells	
Inspection and test	X
Repair of PFBL 141	X
Revamp of PFBL 141	X
Web tension load cells	
Pillowblock tensiometers (PBT)	
Inspection and test	X
Repair	X
Large pillowblock tensiometers (VPBT, HPBT)	
Inspection and test	X
Revamp	X
Exchange load cell	X
Strip scanner edge sensors	
Inspection and test	X
Repair	X
Upgrade	X
Thickness gauges	
Inspection and test	X
Repair of PMGG 113/113-A/123	X
Complete repair of PMGG 113/113-A/123	X
Upgrade of PMGG 122 to PMGG 123-F	X
Exchange unit PMGG 113-A and PMGG 123	X
Repair of gauge holder PMGM 101E/121E	X