

CERTIFICATE OF COMPLIANCE

Certificate Number 20151110-E212323
Report Reference E212323-20110506
Issue Date 2015-November-10

Issued to: ABB Stotz-Kontakt GmbH
Eppelheimer Str 82
69123 Heidelberg GERMANY

**This is to certify that
representative samples of**

CIRCUIT BREAKERS, MOLDED CASE AND CIRCUIT-
BREAKER ENCLOSURES
See addendum page for models

Have been investigated by UL in accordance with the
Standard(s) indicated on this Certificate.

Standard(s) for Safety:

UL489 - Molded-Case Circuit Breakers, Molded-Case
Switches and Circuit-Breaker Enclosures
CSA C22.2 No. 5-13 - Molded-Case Circuit Breakers,
Molded-Case Switches and Circuit-Breaker Enclosures

Additional Information:

See the UL Online Certifications Directory at
www.ul.com/database for additional information

Only those products bearing the UL Certification Mark should be considered as being covered by UL's
Certification and Follow-Up Service.

Look for the UL Certification Mark on the product.



Bruce Mahrenholz, Director North American Certification Program
UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please
contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>



CERTIFICATE OF COMPLIANCE

Certificate Number 20151110-E212323
Report Reference E212323-20110506
Issue Date 2015-November-10

USL/CNL - Cat. Nos. SU20, followed by 1, 2, 3 or 4 followed by MR, followed by -K, followed by 0.2, 0.3, 0.5, 0.75, 1, 1.6, 2, 3, 4, 5, 6, 8, 10, 13, 15, 16, 20, 25, 30, 32, 35, 40, 50, 60, 63, may be followed by additional suffixes.

USL/CNL - Cat. Nos. SU20, followed by 1, followed by PR, followed by -K, followed by 0.2, 0.3, 0.5, 0.75, 1, 1.6, 2, 3, 4, 5, 6, 8, 10, 13, 15, 16, 20, 25, 30, 32, 35, 40, 50, 60, 63, may be followed by additional suffixes.

USL/CNL - Cat. Nos. SU20, followed by 2, 3 or 4, followed by PR, followed by -K, followed by a number from 0.2, 0.3, 0.5, 0.75, 1, 1.6, 2, 3, 4, 5, 6, 8, 10, 13, 15, 16, 20, 25, 30, 32, 35, 40, 50, 60, 63, may be followed by additional suffixes.



Bruce Mahrenholz, Director North American Certification Program
UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>

