

ABB MOTION SERVICES

Workshop repair

Sustainable and high quality repair for your drive



ABB's dust-free and ESD-protected drives service workshops offer the perfect environment to fully repair your drive. From spares replacements to software updates, all work is full-load tested, backed by a two-to-three -year warranty, depending on chosen repair.



Genuine spare parts

Using genuine parts ensures your drive operates as designed. The drive or module is repaired according to the original specification.



Warranty for all repairs

For standard repair ABB provides a two-year warranty for the replaced components. For premium repair ABB provides a three-year warranty for the complete single drive or module.



Cleaning and load testing

Before repair, the drives are thoroughly cleaned, and after repair, tested with a load.



Global network

A global network of ABB authorized drives service workshops offer a consistent approach to the high-quality repair process.



Sustainability & Circularity

Workshop repair service helps to avoid up to 76% in CO₂ emissions as compared to a completely new drive replacement.*)

*) Study conducted by independent environmental consultancy. Comparison based on applicable Carbon Handprint Methodology (2022).



Read more of the <u>service offering</u> and check service availability for your drive with your local ABB representative.



ABB MOTION SERVICES

Workshop repair

Service delivery



Drive failure



Check serial number

Locate the serial number to help quick drive identification.



Contact your local ABB

ABB provides details of your nearest workshop and proposes right solutions for you.



Send broken drive to ABB

If standard repair is selected ABB will send you a repair quotation after inspection.



Workshop repair

ABB repairs your drive only with genuine ABB spare parts. If other maintenance is needed, ABB contacts you with recommendations.



Repaired drive dispatched

After a full-load test, the repaired drive is packed and dispatched back to you.



Drive is running



ABB service report

A detailed service report, including recommendations for future actions, is provided.

ABB

For more information and local contacts, please visit:

www.abb.com/drives
US Motion Services | ABB

or call (800) 752-0696

The information contained in this document is for general information purposes only. While ABB strives to keep the information up to date and correct, it makes no representations or warranties of any kind, express or implied, about the completeness, accuracy, reliability, suitability or availability with respect to the information, products, services, or related graphics contained in the document for any purpose.

Any reliance placed on such information is therefore strictly at your own risk. ABB reserves the right to discontinue any product or service at any time.

© Copyright 2024 ABB. All rights reserved. Specifications subject to change without notice.