
Subject: Knox discontinuation

To whom it may concern,

We ABB, regret to inform that safety lock Knox is no longer possible to manufacture and will become obsolete by end of December 2018.

The reason behind the quick discontinuation is obsolete components; The Eden sensor that is integrated in Knox is no longer available and it has not been possible to replace it with any other safety sensor.

We sincerely apologize for any inconvenience and assure that we are doing everything we can to find a possible replacement solution.

Affected products are:

2TLA020105R2200	Knox 2A v2 Framepart, safelock
2TLA020105R2300	Knox 2X v2 Frame part, processlock
2TLA020105R5000	Knox 1A-R v2 outward open, right
2TLA020105R5100	Knox 1A-L v2 outward open, left
2TLA020105R5200	Knox 1B-R v2 inward open, right
2TLA020105R5300	Knox 1B-L v2 inward open, left
2TLA020105R5800	Knox 1AX-R v2 outward open, right
2TLA020105R5900	Knox 1AX-L v2 outward open, left
2TLA020105R6000	Knox 1F-R v2 sliding door to right
2TLA020105R6100	Knox 1F-L v2 sliding door to left
2TLA020105R6200	Knox 1BX-R v2 inward open, right
2TLA020105R6300	Knox 1BX-L v2 inward open, left
2TLA020105R6400	Knox 1FX-R v2 sliding door to right
2TLA020105R6500	Knox 1FX-L v2 sliding door to left

Kungsbacka 2018-09-15



Elias Agrell
GPM Product Line Safety Products
ABB Jokab Safety

ABB AB
Varlabergsvägen 11
434 39 Kungsbacka, Sweden
Phone: +46 300 56 43 19
E-mail: elias.agrell@se.abb.com
Web: www.abb.com/jokabsafety